

Part number	Date of visit to the dealer	Mileage	Dealer number	Type
	27.02.2019	142683 km	31585/03	
	<i>info: No repair log entries</i>			
	27.02.2019	135441 km	31585/03	
	<i>info: No repair log entries</i>			
	03.05.2017	130417 km	31585/03	
	<i>info: No repair log entries</i>			
	22.12.2016	127961 km	32892/01	
	<i>info: No repair log entries</i>			
	09.02.2016	117510 km	31585/03	
	Vehicle adoption			
	Performing a car check			0
	Service due / to be carried out			
	Maintenance "Brake fluid"			6
	Maintenance in the usual scope			2
83132184843	Brake fluid DOT4 LV, Low viscosity			1
34216758059	Retaining spring			1
	Vehicle - wash			
	!!! unknow BMW-id 0011393 Wash vehicle without calculation and vacuum out footwell !!!			2
	02.11.2015	190172 km	04107/09	
	<i>info: No repair log entries</i>			
	14.01.2013	107301 km	00866/01	
	E60 E61 E63 E64 Check battery cable cover			
	Checking and, if necessary, adjusting, installing the battery cable cover			5
61139290787	Protective cap plus battery poles			1.0
	14.01.2013	107301 km	00866/01	

	Service the front screen. Vacuum the front footwell			4
	14.09.2012	106477 km	34007/01	
	24 hour service			0
	Vehicle Diagnostics - Test Module Execution			6
	Performing a car check			4
	Check engine oil and cooling water including frost protection. Fill level YES () NO (x)			0
	13.09.2012	106471 km	34007/01	
	<i>info: No repair log entries</i>			
	09.05.2012	106099 km	04413/01	
	Operating hours not set / Body equipment			10
	Replacing left or right rear side window			18
51357186644	Side window right, Gruen			1
	30.05.2011	79836 km	02248/01	
	<i>info: No repair log entries</i>			
	29.11.2010	60307 km	02248/01	
	<i>info: No repair log entries</i>			
	12.08.2010	48432 km	34985/04	
	<i>info: No repair log entries</i>			
	30.04.2010	37419 km	20433/04	
	<i>info: No repair log entries</i>			
	29.09.2008	32042 km	10157/01	
	Rear lid seals Water ingress/ condensate			
	Speakers Unpleasant noises			
	Removing and installing / replacing left and right center woofers			14
	Removing and installing / replacing left and right center woofers			0
65139143132	Center woofer, right			1.0

65139143131	Center woofer left			1.0
	29.09.2008	31228 km	10157/01	
	<i>info: No repair log entries</i>			
	24.09.2008	31228 km	10157/01	
	Speakers Unplesant noises			9
	04.12.2007	28510 km	10157/01	
	<i>info: No repair log entries</i>			
	27.11.2007	27152 km	10157/01	
	<i>info: No repair log entries</i>			
Vehicle information				
VIN	WBAKS61090XXXXXX			
Type	EK31			
Production date	2007-01-10			
Model code	E64 ()			
Model	630I (EUR)			
Body type	Cabriolet, 2 doors (Cab)			
Engine	N52			
Displacement, l	3.00			
Power, KW	190			
Gearbox	Automatic (AUT)			
Drivetrain	Rear-wheel drive (HECK)			
Steering	Left hand drive (LL)			
Body colour	BLACK SAPPHIRE METALLIC (475)			
Upholstery	LEDER DAKOTA/SCHWARZ (LCSW)			
S255A	Sports leather steering wheel			
S431A	Interior mirror with automatic-dip			
S459A	Seat adjustment, electric, with memory			
S502A	Headlight cleaning system			
S522A	Xenon Light			

S534A	Automatic air conditioning
S548A	Kilometre speedo
S676A	HiFi speaker system
S851A	Language version German
S1CAA	Selection of COP-relevant vehicles
S205A	Automatic transmission
S302A	Alarm system
S320A	Deleted, model lettering
S346A	Chrome Line exterieur
S356A	Climate comfort laminated glass
S387A	Wind deflector
S388A	Softtop, black
S423A	Floor mats velours
S428A	Warning triangle and first aid kit
S430A	Interior/outside mirror with auto dip
S436A	Fine wood trim
S442A	Drink holder
S464A	Ski bag
S494A	Seat heating driver/passenger
S5ACA	High-beam assistant
S508A	Park Distance Control (PDC)
S540A	Cruise control
S563A	Light package
S593A	BMW LA wheel/double spoke 120
S672A	CD changer for 6 CDs
S698A	Area-Code 2 for DVD
S8SAA	Navigation access request,country-spec.
S8SPA	Control unit COP
S863A	Dealer List Europe
S879A	On-board literature, German
S896A	Daytime driving lights