

Dealer History	Date	Mileage (km)	Order no .:	Account No .:
	2018-02-05	402131 km	1800038001	32001060
	1 10121799 AdBlue - Auffüllen - 0000 0			
	1 G 052910S0 UREA 14.00 S OWN F 0 0			
	2013-01-30	154881 km	187648	43841621
	Customer complaint	Em (2013-01-30 09:02): Heating in the passenger compartment without function		
	Customer complaint coding	Air conditioning> Heating, cooling> Additional heating Station conclusion		
	Station conclusion	Error code N317 Heat exchanger shut-off valve 2		
	Dealer Coding	No repair		
	Spare part for troubleshooting			
	2012-06-20	109889 km	183701	38694654
	Customer complaint	Em (2012-06-20 08:48): Injection control lights up		
	Customer complaint coding	Information, navigation, communications, entertainment> Fault indicators in the form of pictograms> Fault indication of the exhaust control system> Functionality> triggered		
	Station conclusion	Tester VAS5052A did not work properly, had to be turned off therefore protocol from 27.6.2012 not complete		
	Dealer Coding	Engine> Exhaust, Recirculation, Exhaust Gas Cleaning> Exhaust Radiator		
	Spare part for troubleshooting	03l-131-512-cf		
	2012-05-02	102603 km	182729	37608684
	Customer complaint	Em (2012-05-02 11:20): AdBlue lights up, although it was refilled first		
	Customer complaint coding	Information, navigation, communications, entertainment> Control indicators in the form of pictograms> Control indications of a low level of the restorer> Functionality> false positives		
	Station conclusion	[2025056/1 7N, control lamp lights up, event memory entries P229F and / or P20EE stored]		
	Dealer Coding	Repairs according to TPI		
	Spare part for troubleshooting	8k0-907-807-c-		
	2012-01-16	83820 km	180517	35266409
	Customer complaint	Em (2012-01-16 16:02): Engine cover broken		

	Customer complaint coding	Curtain elements> Sound and thermal insulation> Engine compartment tray> Part / working fluid> damage		
	Station conclusion	broken or broken break points due to engine vibrations, engine cover renewed		
	Dealer Coding	Engine> Cylinder block, crank mechanism> Engine console		
	Spare part for troubleshooting	03l-103-925-at		
	2012-01-16	83820 km	180517	35266501
	Customer complaint	Em (2012-01-16 16:04): driver sun visor no LichtEm (2012-01-16 16:02): Engine cover broken		
	Customer complaint coding	Curtain elements> Interior rearview mirror, sun visors and curtains> Sun visor		
	Station conclusion	No light at driver's sun visor, electr. error		
	Dealer Coding	Curtain elements> Interior rearview mirror, sun visors and curtains> Sun visor		
	Spare part for troubleshooting	7m3-857-551-q2-f4		
	2012-01-16	83820 km	180517	35941638
	Customer complaint	Em (2012-02-14 11:39): noise left front,		
	Customer complaint coding	Chassis> Suspension> Stabilizer Rack		
	Station conclusion	Stabigelenk is worth it		
	Dealer Coding	Chassis> Suspension> Stabilizer rack> Parts / assemblies, hydraulic fluids> dar		
	Spare part for troubleshooting	1k0-411-315-k-		
	2011-04-28	29867 km	175394	29899519
	Customer complaint	Em (2011-04-28 07:33): Range indicator for particle filter permanently on		
	Customer complaint coding	Information, navigation, communications, entertainment> Indicators indications in the form of icons> Display: diesel particulate filter> Functionality> does not turn off / does not turn off		
	Station conclusion	-		
	Dealer Coding	Engine> Exhaust, Recirculation, Exhaust Gas Cleaning> Reducing Pump		
	Spare part for troubleshooting	2e0-919-050-s		
	2011-04-22	29867 km	175254	29828060
	Customer complaint	Em (2011-04-22 07:49): Action 58B6		
	Customer complaint coding	Power supply, onboard network, data transmission		
	Station conclusion	-		
	Dealer Coding	Power supply, onboard network, data transfer> Data transfer buses		

	Spare part for troubleshooting		-			
	2010-12-21	1230 km	173045	27519158		
	Customer complaint		Em (2010-12-21 09:11): Sliding doors can not be opened from the outside, control does not go out immediately.			
	Customer complaint coding		Curtain elements> Control doors, covers, hood> Sliding door closer			
	Station conclusion		according to their info repaired			
	Dealer Coding		Curtain elements> Doors> Door lock> Executive motor for locking the door lock			
	Spare part for troubleshooting		7N0-839-100-B			
Service activities	Event	Start	Name	Date of repair	Criterion	Done
	S363	2016-12-30	Filling up Adblue® (Information in 23S1)	-	04, 05	No
	23Q6	2015-10-01	S-Service campaign for diesel exhaust gas EA189	2017-02-10	03, 53	Yes
	23S1	2016-04-12	A-Engine Control Unit (NOx)	2017-02-10	13	Yes
Vehicle information	VIN: VSSZZZ7NZBXXXXXXX					
	Brand: S					
	Model Year: 2011					
	Model: 710363					
	Engine code: CFFB					
	Letter code of gearbox: LTA					
	Description: ALHAMBRA suc.Style 103 TDID6F					
	Date of production: 2010-09-11					
	Date of transfer to the customer: 2010-10-28					
	Number of type approval:					

	Registration: 2010-10-28
	The next TRP: 2017-10
	The following exhaust gas control: 0000-00-00
	Code of the country: AUT
	Region: 605, 219
	Dealer number: 05406
Color performance	
	External: 7B/7B
	Inside: JL
	Description: LR7L
	Silver Leaf Metallic/Silver Leaf Metallic
	Palladium Gray/Titanium Black/Black/ Pearl Gray
0AG L STV Front stabilizer	
0BB L STH Rear stabilizer	
0ES L EDF Installation differentiation for transmission DQ250 vehicle components	
0F5 L KRS Fuel system for diesel engine	
0FA L FAD Standard manufacturing sequence	
0NB L SZU Nameplate set in base trim	
0TD L ZFM Front and rear floor mats	
0VC L BTA Information kit in German	
0Y1 L KLZ Standard climatic zones	
0YE L GKH Weight range 5 installation control only, no requirement forecast	
0Z4 L FIB SEAT marque-specific/class-specific features	
1AT L BRS Electronic stabilization program (ESP)	
1D0 L AHV Without trailer hitch	
1E0 L AKB Without activated charcoal canister	

1EX L TYP Special identification plate for EC for M1 passenger vehicle
1JA L DFH Rear shock absorption, basic design 1
1LW L BAV Disc brakes, front
1N3 L LEN Speed-related variable steering assist (Servotronic)
1NL L RAA Covers for alloy wheels
1PE L ABR Wheel bolts with anti-theft protection (unlockable)
1Q1 L TGL Mass damper for steering wheel, 26.5Hz
1SA L TWU Without additional front underbody guard
1T0 L VBK Without first aid kit and warning triangle
1U9 L KLT Folding table on front seat backrests
1X0 L ATA Front wheel drive
1Z0 L KRM Initial standard fuel filling
2A0 L UEA Without delivery equipment
2FQ L LRA Leather trimmed multi-function sports steering wheel w/ Tiptronic
2H0 L CHA Without "drive select"
2KW L SAU Labels/plates in German, French, and Dutch
2UA L SWP Standard design
2WA L ZBR Without additional tires
3CX P TRW Net partition
3FA L DEI Without roof insert (standard roof)
3H2 L LER Backrest release for right front seat
3LC L TSV Door and side trim panel in foam film and woven fabric
3M0 L SZL Without special measures
3PD L SIE Manual height adjustment for front seats, electric backrest adjustment for left front seat
3S1 L DAR Bright roof rails
3SB L SFR Standard seat, front right
3TB L SFL Standard seat, front left
3U4 L GPR Luggage compartment cover
3W4 L GDM Acoustics package "Standard"
3Y7 L SSR Roll-up sun screen

4A3 P SIH Seat heater for front seats separately controlled
4E7 P SDH Trunk lid power closing
4GF L WSS Windshield in heat-insulating glass
4H5 L KDS Electrically operated child lock
4K3 L TKV Radio remote controlled central locking operated from inside and safe securing
4KF P SSH Side windows in heat-insulating glass, from B-pillar and rear window dark tinted
4L6 L IRS Breakaway interior rear view mirror, automatically dimming
4M5 L BEH Cup holder
4N2 L INT Standard dashboard
4SR L MSL Left vanity mirror illuminated
4TR L MSR Right vanity mirror illuminated
4UP L AIB Driver's and front passenger air bag with knee air bag and front passenger air bag deactivation
4X3 L SAB Side air bag front with curtain air bag
4Y1 L VSS Storage compartment
4ZB L ZIE Bright moldings
5D1 L TRF Carrier frequency 433.92 MHz-434.42 Mhz
5K7 L LAC Transport protection film (minimum protection) with additional transport protection measures
5KP L HIS 3 separate seats (first row of seats)
5MJ L EIH Decorative inserts
5RQ L ASR Right exterior mirror: convex
5SL L ASL Left exterior mirror: aspherical
5ZF L KOV Front headrests
6A0 L FEU Without fire extinguisher
6KJ L KUG Radiator grille with chrome-plated strip
6L6 P CHS C-rails on side panel
6M3 P GPS Trunk net
6P1 L KZH License plate carrier rear (ECE)
6Q2 L SAG Leather gearshift knob/handle
6T0 L INL Without interior light in footwell
6W1 L KZV License plate carrier front (large)

6X0 L HGE Without entry grab handle
6XQ P ASE Exterior mirrors: with memory function, electrically foldable/adjustable, separately heated
7A0 L CDW Without CD changer/CD player
7AA L EDW Electronic vehicle immobilization device
7B2 L STD 12-volt socket in luggage boot
7E0 P WSA W/o heat accumulator/auxiliary heating
7KM L AED Vehicle class differentiation -710-
7L6 L SNA Start/stop system with regenerative braking
7MG L AGM Emission standard EU5
7N1 L ALS Tray on roof liner
7P7 L LOR Electrically adjustable lumbar support for left front seat
7Q0 L NAV Without navigation device
7QA L CDR Without CD/DVD for navigation
7X2 P EPH Park distance control, front and rear
8AE L RAO Radio "RCD310 MP3"
8G1 P LIA High beam assistant
8GV L GEN Alternator 180 A
8ID L HSW Halogen twin headlights
8K3 L FLS Separate daytime running lights with low beam assistant and "Coming Home" feature
8N3 L SWS Windshield wiper intermittent control with rain sensor
8Q1 L LWR Headlight-range adjustment
8QE L SLR Key for locking system with remote control
8RM L LSE 8 speakers (passive)
8S7 L LEL Two reading lights front
8SA L SBR Taillight assemblies, standard design
8T2 L GRA Cruise control system (CCS) electronic
8TC L NEL Rear fog light for driving on the right
8WH L NES Front fog lamp and cornering lamp
8X1 P SWR Headlight washer system
8Z5 L MKU Not hot country

8ZH L ANT Antenna for AM/FM reception, "diversity"
9A0 L TAA Without taxi alarm system
9AH P HKA Climatronic with second evaporator and second heating system
9JA L RAU Non-smoking package
9M5 P ZUH Auxiliary heater
9P3 L SGK Seat belt reminder, electric contact in buckle
9Q5 L MFA Multi-function display with control
9T1 P BWD Heated washer nozzles, front
9TC L WAL Additional reflectors (door area)
9W0 L VTV W/o car phone preparation/installation
9WL L AUD Multimedia socket for external audio source
9Z3 P BTR Operating voltage 12 V plus 230 inverter
A8C I AUS Comfort equipment
AV1 L LRV Driving on the right
B0A L BLB Component parts set without country-specific design requirement
B12 L TPL Type approval Austria
C01 E COC Operating permit, alteration
CS0 L RAD Alloy wheels 6.5J x 16
D91 I MOT 4-cyl. turbo diesel engine 2.0 l/103 kW (4V) TDI common rail; Base engine: TG3/
TJ3/TU3/TU4/TL4/TP4/TM3/TW3/TR4/TS1/TN5
E0A L AAU No special edition
F0A L FZS No special purpose vehicle, standard equipment
FC0 L IND Without customized installation
FS5 L ADS 5 seats
G02 L DFV Front shock absorption
G1A I GSP 6-speed automatic transmission
GZ6 P EST Electric. operated sliding door lh & rh plus power latching
H09 L REI Tires 215/60 R16 95H (polymer coating)
J2D L BAT Battery 380 A (68 Ah)
K8P I KAR MPV

L02 L GKV Suspension range 02 installation control only, no requirement forecast
L0L L LEA Left-hand drive vehicle
N0U L SIB Cut pile seat covering
NT0 L TSP Transit coating (type 1)
NY0 L BGK Standard battery/alternator capacity
PCD G Puerta corredera electrica
PCO G Cristales oscuros
PCP G Cargo Package
PH1 G Climatronic
PIS G Precio especial
PW1 G Paquete invierno
QA0 L KIS Without child seat
QE0 L ALG Without tray areas package/box
QG1 L WIV Service interval prolongation
QJ1 L CHR Chrome work package
QN3 L SVS Drawers under front seats
QV0 L TVE W/o TV reception/digital radio reception
S0C E SNR Introductory volume
SD9 P SNR Special price
TL4 I GMO 4-cylinder diesel engine 2.0 I unit 03L.L
U5A L INS Instrument insert, km/h speedometer
UF6 L ESS Electric interface for external use (MDI)
UH2 P FSB Parking brake
WD1 G technology Package I
X4A G National sales program Austria